2020年3月16日

アドバンテック株式会社

# IPCシャーシ、及びACPシャーシ製品型番変更のお知らせ

平素は格別のご高配を賜り、厚く御礼申し上げます。

この度、年末に失効する安全性規格 UL/IEC 60950から新規格であるUL/IEC62368への対応のため、IPCシャーシ、及びACPシャーシ製品型番が変更となります。

ここにご案内申し上げます。

記

**（1） 対象製品型**

| | | | |
|---|---|---|---|
| ACP-2000EBP-00BE | ACP-2000EBP-00BE | ACP-2000EBP-00BE | ACP-2000EBP-00BE |
| ACP-2000P4-00BE | ACP-2000P4-00BE | ACP-2000P4-00BE | ACP-2000P4-00BE |
| ACP-2010MB-00CE | ACP-2010MB-00CE | ACP-2010MB-00CE | ACP-2010MB-00CE |
| ACP-2010MB-25CE | ACP-2010MB-25CE | ACP-2010MB-25CE | ACP-2010MB-25CE |
| ACP-2010MB-35CE | ACP-2010MB-35CE | ACP-2010MB-35CE | ACP-2010MB-35CE |
| ACP-2320MB-00CE | ACP-2320MB-00CE | ACP-2320MB-00CE | ACP-2320MB-00CE |
| ACP-2320MB-25CE | ACP-2320MB-25CE | ACP-2320MB-25CE | ACP-2320MB-25CE |
| ACP-2320MB-35CE | ACP-2320MB-35CE | ACP-2320MB-35CE | ACP-2320MB-35CE |
| ACP-2020MB-35ZE | ACP-2020MB-35ZE | ACP-2020MB-35ZE | ACP-2020MB-35ZE |
| ACP-4000BP-00CE | ACP-4000BP-00CE | ACP-4000BP-00CE | ACP-4000BP-00CE |
| ACP-4000BP-30CE | ACP-4000BP-30CE | ACP-4000BP-30CE | ACP-4000BP-30CE |
| ACP-4000BP-40CE | ACP-4000BP-40CE | ACP-4000BP-40CE | ACP-4000BP-40CE |
| ACP-4000BP-50CE | ACP-4000BP-50CE | ACP-4000BP-50CE | ACP-4000BP-50CE |
| ACP-4000MB-00CE | ACP-4000MB-00CE | ACP-4000MB-00CE | ACP-4000MB-00CE |
| ACP-4000MB-30CE | ACP-4000MB-30CE | ACP-4000MB-30CE | ACP-4000MB-30CE |
| ACP-4000MB-40CE | ACP-4000MB-40CE | ACP-4000MB-40CE | ACP-4000MB-40CE |

## （2） 変更実施スケジュール




| Important Date | Description | Date |
|---|---|---|
| Announcement | Announcement of this document | **2020/3/16** |
| Sales Feedback | Sales feedback if customer has any problem to follow the schedule. It will be treated as special case | **2021/1/31** |
| Forecast Frozen | The forecast will be frozen for material preparation | **2021/2/10** |
| Phase-out | The product is officially phased out. | **2021/2/28** |
| LTB | Last time buy for customer order. After this date, no more order will be accepted. | **2021/2/28** |
| Last Shipment | Acceptable shipment date before LTB. The order with requesting DD after this date will not be accepted. | **2021/5/31** |

**Note: 変更予定時期はあくまで予測に基づくものです。実際の変更時期は前後する場合があります。**

## (3)後継機種情報

| End of Life Product | Replacement Product | Replacement Product Available Date |
|---|---|---|
| **ACP-2000EBP-00BE** | ACP-2000EBP-00C | By 2020/5/31 |
| **ACP-2000P4-00BE** | ACP-2000P4-00C | By 2020/5/31 |
| **ACP-2010MB-00CE** | ACP-2010MB-00D | By 2020/5/31 |
| **ACP-2010MB-25CE** | ACP-2010MB-25D | By 2020/5/31 |
| **ACP-2010MB-35CE** | ACP-2010MB-35D | By 2020/5/31 |
| **ACP-2320MB-00CE** | ACP-2320MB-00D | By 2020/5/31 |
| **ACP-2320MB-25CE** | ACP-2010MB-00D + PS8-250FATX-BB | By 2020/5/31 |
| **ACP-2320MB-35CE** | ACP-2320MB-35D | By 2020/5/31 |
| **ACP-2020MB-35ZE** | ACP-2020MB-35B | By 2020/5/31 |
| **ACP-4000BP-00CE** | ACP-4000BP-00F | By 2020/5/31 |
| **ACP-4000BP-30CE** | ACP-4000BP-30F | By 2020/5/31 |
| **ACP-4000BP-40CE** | ACP-4000BP-50F | By 2020/5/31 |

| | | |
|---|---|---|
| **ACP-4000BP-50CE** | ACP-4000BP-50F | By 2020/5/31 |
| **ACP-4000MB-00CE** | ACP-4000MB-00F | By 2020/5/31 |
| **ACP-4000MB-30CE** | ACP-4000MB-30F | By 2020/5/31 |
| **ACP-4000MB-40CE** | ACP-4000MB-50F | By 2020/5/31 |
| **ACP-4000MB-50CE** | ACP-4000MB-50F | By 2020/5/31 |
| **ACP-4010BP-00BE** | ACP-4010BP-00C | By 2020/5/31 |
| **ACP-4010MB-00BE** | ACP-4010MB-00C | By 2020/5/31 |
| **ACP-4020BP-25ZE** | ACP-4020BP-50B | By 2020/5/31 |
| **ACP-4020BP-30ZE** | ACP-4020BP-50B | By 2020/5/31 |
| **ACP-4020BP-40ZE** | ACP-4020BP-50B | By 2020/5/31 |
| **ACP-4020MB-25ZE** | ACP-4020MB-30B | By 2020/5/31 |
| **ACP-4020MB-30ZE** | ACP-4020MB-30B | By 2020/5/31 |
| **ACP-4020MB-40ZE** | ACP-4020MB-50B | By 2020/5/31 |
| **ACP-4020MB-70ZE** | ACP-4020MB-70B | By 2020/5/31 |
| **ACP-4320BP-00BE** | ACP-4320BP-00C | By 2020/5/31 |
| **ACP-4320BP-40BE** | ACP-4320BP-00C + PS8-500ATX-BB | By 2020/5/31 |
| **ACP-4320BP-50BE** | ACP-4320BP-00C + PS8-500ATX-BB | By 2020/5/31 |
| **ACP-4320MB-00BE** | ACP-4320MB-00C | By 2020/5/31 |
| **ACP-4320MB-25BE** | ACP-4320MB-00C + PS8-250ATX-ZE | By 2020/5/31 |
| **ACP-4320MB-40BE** | ACP-4320MB-50C | By 2020/5/31 |
| **ACP-4320MB-50BE** | ACP-4320MB-50C | By 2020/5/31 |
| **ACP-4340BP-40ZE** | ACP-4340BP-50B | By 2020/5/31 |
| **ACP-4340BP-50ZE** | ACP-4340BP-50B | By 2020/5/31 |
| **ACP-4340BP-70ZE** | NA | By 2020/5/31 |
| **ACP-4340MB-40ZE** | ACP-4340MB-50B | By 2020/5/31 |
| **ACP-4340MB-50ZE** | ACP-4340MB-50B | By 2020/5/31 |
| **ACP-4340MB-70ZE** | ACP-4340MB-70B | By 2020/5/31 |
| **ACP-4360MB-00XBE** | ACP-4360MB-00C | By 2020/5/31 |
| **IPC-510BP-30CE** | IPC-510BP-30F | By 2020/5/31 |
| **IPC-510MB-30CE** | IPC-510MB-30F | By 2020/5/31 |
| **IPC-510MB-40CE** | IPC-510MB-50F | By 2020/5/31 |
| **IPC-510MB-30ZCE** | IPC-510MB-30ZF | By 2020/5/31 |
| **IPC-510MB-40ZCE** | IPC-510MB-50ZF | By 2020/5/31 |
| **IPC-510BP-40ZCE** | IPC-510BP-00XCE + PS8-500ATX-BB | By 2020/5/31 |
| **IPC-603MB-35BE** | IPC-603MB-35C | By 2020/5/31 |
| **IPC-610BP-00LBE** | IPC-610BP-00LD | By 2020/5/31 |
| **IPC-610BP-50LBE** | IPC-610BP-00LD + PS8-500ATX-BB | By 2020/5/31 |
| **IPC-610MB-00LBE** | IPC-610MB-00LD | By 2020/5/31 |
| **IPC-610MB-40LBE** | IPC-610MB-50LD | By 2020/5/31 |
| **IPC-610BP-00XHE** | IPC-610BP-00HD | By 2020/5/31 |
| **IPC-610BP-30HBE** | IPC-610BP-30HD | By 2020/5/31 |
| **IPC-610BP-40HBE** | IPC-610BP-50HD | By 2020/5/31 |

| | | |
|---|---|---|
| **IPC-610BP-50HBE** | IPC-610BP-50HD | By 2020/5/31 |
| **IPC-610MB-00XHE** | IPC-610MB-00HD | By 2020/5/31 |
| **IPC-610MB-30HBE** | IPC-610MB-30HD | By 2020/5/31 |
| **IPC-610MB-40HBE** | IPC-610MB-50HD | By 2020/5/31 |
| **IPC-610MB-50HBE** | IPC-610MB-50HD | By 2020/5/31 |
| **IPC-611MB-00XBE** | IPC-611MB-00C | By 2020/5/31 |
| **IPC-611BP-00XBE** | IPC-611BP-00C | By 2020/5/31 |
| **IPC-631MB-50ZE** | IPC-631MB-50B | By 2020/5/31 |
| **IPC-631MB-70ZE** | IPC-631MB-70B | By 2020/5/31 |

**（3） 変更詳細**

安全性規格 UL/IEC 60950が年末に失効するため、新規格であるUL/IEC62368への対応のため電源、及びファン(PWM)が変更になります。

尚、 本ご案内に関するお問合せは、次のようにお願い致します。

- 販売代理店様からご購入された場合
  - ― 販売代理店様へお問い合わせください。
- ご購入いただいた販売代理店様がわからない場合、弊社から直接ご購入された場合
  - ― 以下弊社窓口へ直接お問い合わせください。

アドバンテック株式会社マーケティング部
〒111-0032東京都台東区浅草6-16-3
E-mail: ajp_callcenter@advantech.com
TEL: 0800-500-1055 (フリーダイヤル) FAX: :03-6802-1022